

Footpath number	Description	Initial review summer 2018	Summer 2019
RP1	RP1 is the track up from off the left of the Towcester Road and runs east out of the village. It becomes RF12 (another jurisdiction - Buckinghamshire according to the footpath marker) at the end of the track - 1st stile you come to.	This stile looks fine and robust and well marked. There is a footpath signpost at the entrance to the track so no issues with this footpath.	14-Sep-19. Walked, all fine.
RP2	RP2 starts on the Northampton Road, by the playing field and travels out of the back of the playing field, behind the industrial units and across the 'potato field' to the brook. The other side of the brook is footpath FE5, another jurisdiction.	At the start of the 'potato field' there is no marker showing the route into or through this field. There is a gap in the shrubs/hedging which looks like the route the footpath takes but there is no marker nor anywhere to put a marker. The remainder of the footpath is fine.	Beyond the industrial site and beyond the first field there is no sign to show the route into the 2nd field although there is a route through. Steps have been built to enable walkers to continue beyond the 2nd field along this footpath.
RP3	RP3 runs from beyond the last house on the right (East) of Farthingstone road heading away from Litchborough. It runs north until it hits the brook and becomes FE4 on the other side of a small bridge. FE4 belongs to another footpath jurisdiction.	On first review we walked west along the brook from the end of RP2 to join the beginning of RP3. So we walked South to meet the Farthingstone road. The only issue we found was the need for a marker on the entrance to the last field.	To check: marker into last field approaching last field (walking south) still needs affixing.
RP4	RP4 forks off RP16 in a north westerly direction where RP5 continues in a south westerly direction. We're not exactly sure of the point but it appears to be near the first stile.	All looked fine but we weren't able to get to the farthest point as there were a lot of interested cows! So we still need to get to the end to check markers, etc.	10-Sep-19: Walked first two of three fields, Suspected bull in third field so still need to get to the end of the footpath to check entry markers from ES1 (other footpath jurisdiction).
RP5	RP5 extends from the end of RP16 in a south westerly direction toward the Banbury Road (we think).	Beyond RP16, RP5 has a further stile which is robust, we just replaced the footpath marker. The route to the next stile is clear once the crop is cleared. The next stile has been removed following Gwen and I reporting it as broken. RP5 terminates at the main road where there is a gate (we cut back some of the shrubs as some walkers said it was difficult to open the gate) which we think is the Banbury Road.	10-Sep-19. Walked, all fine.
RP6	RP6 is a short footpath starting farther along the main road just up from where RP5 meets the road.	All seemed fine although there are no markers showing the change of the footpath and jurisdiction to ES3 but not sure that is a concern.	10-Sep-19. Walked, all fine.
RP7	Does not exist		
RP8	RP8 starts beyond Hay Barn on the right of the Towcester Road heading West. The footpath has a post showing the start and stiles taking the walker to along the wall which is the 'official' route for the footpath.	However there is a track that is a more obvious route and intrudes less on the Hay Barn land. At the end of the wall there is another stile. RP8 continues straight on crossing RP9 (stile, we added a marker) and travelling down to the Banbury Road just beyond the last house on the left as you go out of the village. There is no stile here but a stone which assists climbing over the fence.	4-Sep-19: All of the footpath is fine. An application has been entered to change the route of the footpath to as described in our initial review which seems sensible. This request has met with no objections as is expected to be confirmed.
RP9	RP9 is a long footpath and starts behind the village green and heads south along the east side of the old cricket pitch. It meets RP10 and forks right (south west and crosses RP8 (stile) and heads west (north of Tivy Farm) and then takes a sharp left (south) and passes a pond on its left (west of Tivy Farm) and hits the top road. The footpath continues beyond the top road south (it is signposted to the south and north) to a field delimiter just beyond some farm buildings and hits footpath RC11 which is a different jurisdiction.	Checked and all fine.	4-Sep-19: All checked north of the top road and expected to be fine south toward RC11 as very wide track.

Footpath number	Description	Initial review summer 2018	Summer 2019
RP10	RP10 starts about two thirds of the way along RP9 from behind the green on the east side of the old cricket pitch. See above. RP10 crosses RP8 (see above) and continues south (east of Tivy farm) and hits the top road. The continuation of RP10 (it is signposted) south of the top road is a hundred yards or so along the top road (west). RP10 runs parallel to RP9 also hitting RC11. At this point, RP10 is signposted heading north.	Initially there was no gap in the hedge on the top road but this was rectified.	4-Sep-19: Walked and all fine. Access to the south from the top road is uneven but this is to be expected with footpaths. Further, the entry to RP11 less than 100 yards along the road can be used.
RP11	RP11 starts on the top road about 100 yards the other side of the continuation of RP10 (it is signposted) and travels south east until it hits the single track road that takes you from the Towcester Road past Foxley Lodge and Foxley House to Banbury Lane. There is a bit of a stile and a slab of concrete which are enough to gain access from the top road.		4-Sep-19: Cut back the foliage at the Foxley Lodge end of the footpath, the single track road. All fine.
RP12	RP12 is a short footpath from the start of the single track road to Foxley, to the Caswell Road, thus cutting off the corner.	There are no signposts, delimiters or post markers at either end of the footpath. As it is not much farther to walk along the Towcester Road and up Caswell Road. Although we reported this (1624983), it is agreed with the Rights of Way Officer that further action is low priority.	No change.
RP13	RP13 is off the single track road to Foxley, from just before Foxley Lodge, west toward Seawell farm/reserve and RC11 and RC15.		Walked 14/5/2019. Not entirely clear where it changes to RC15 so put a marker facing toward the lane at the bridge. Put a marker on the post at the gate end too.
RP14	RP14 is off the single track road but from beyond Foxley House in a south easterly direction.	It is signposted 'Knightley Way' (finger post), is well marked across the field and there is another fingerpost at the Banbury Road end.	15-Sep-19: Crop harvested and field ploughed so route across no longer obvious. Can walk across or around the perimeter of this field.
RP15	RP15 is a tiny footpath North East of the village, off the Northampton Road toward the A5, beyond Radmore Farm. Slightly wobbly sign post (top metal tie has broken) and grubby but visible.	The bridge, although robust, was 'old style' and needs replacing. Left hand rail wobbly (reported). There is a sign on the entrance to the field saying there is a bull in the field, which is fine. The footpath hits RF14 which is another jurisdiction. Both ends of the footpath have finger post signs. The stile over to RF14 is robust.	To be walked.
RP16	RP16 is the start of the Knightly Way up Kiln Lane off the Banbury Road.	All fine and signposted.	10-Sep-19. Walked, all fine.